0043



Tile respossors
#5

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

26 March 1992

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

DECEMBER 1

APR 0 1 1992

DIVISION OF OIL GAS & MINING

Dear Pamela:,

Re: NOV # N92-40-7-1, Ditch D-9U & Lump Coal, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025, Emery County, Utah

This letter is to inform the Division that all lump coal has been removed from on top of the berm of ditch D-9U. Location of the lump coal storage pile is being reviewed. Any proposed modifications to the mine plan will be submitted to the Division.

Please notify me or Charles Reynolds when you wish to review the on-site work and notify me if there are any open issues concerning abatement of this violation.

Thank you,

Kimly C. Mangum, P.E.

cc:

Co-Op Mining Co.